# Sight Flow Indicators (straight line) with heating jacket



Bauform 880-HM

## **Application:**

To keep cold- or heat- loss at sight flow indicators as low as possible, they are surrounded with a heating jacket. Within the resulting cavity, a corresponding medium can flow to avoid cold- or heat- loss.

### **Dimension:**

Body corresponds Bauform 880 Measures see at Bauform 880 With DIN- and ANSI - Flanges All dimensions and all pressures

#### Materials:


Body: WN 1.4408 Heating jacket: WN 1.4571

## **Connections for heating jacket:**

Buttweld ends Inside or outside thread Flange connection Screwing

## Standard design:

Inside thread acc. to sketch



Butt weld ends	Inside or outside thread	Flanged connections

Modifications reserved

